

Onboard 2013 Builds

Note: some builds listed below may be in beta testing, or may not have been made generally available.

Changes in version 2013.r1.2112 (24/03/2014)

New features

- › Enhancement to UI lock down mode

Changes in version 2013.r1.2111 (28/02/2014)

Bug Fixes

- › Very rare occurrences of audio clicking
- › In some circumstances, zeroes at end of recorded audio

Changes in version 2013.r1.2109 (25/02/2014)

New features

- › Presets
- › New sysconfig “OnboardUiLockDown”
- › New sysconfig IgnoreVPIDLinkId

Changes in version 2013.r1.2108 (07/10/2013)

New features

- › ARRI metadata may now be recorded from the Alexa in HD video modes

Bug Fixes

- › Corruption of compressed video data on some Onboards
- › Dropped video frames in 4K CANONRAW at 60fps with high detail images
- › Fixed video signal detection check (broken in the previous build)
- › TC Drop frame flag was being lost during TC rate conversion

Changes in version 2013.r1.2107 (26/04/2013)

New features

- › New sysconfig “OnboardRingEtoEColour” to override default amber colour

Bug Fixes

- › LookLutMode set incorrectly when look doesn't contain a LUT
- › LookFile should contain None rather than empty string if no look loaded

Changes in version 2013.r1.2104 (17/04/2013)

New features

- › New sysconfig “DisableUnloadOnDoorOpen” for Onboard S
- › Made it possible to format drives containing an unrecognised filesystem

Bug Fixes

- › Set CdlApplicationMode to ARRI_LOOK_NONE if no CDL set

Changes in version 2013.r1.2102 (27/03/2013)

New features

- › New warning “timecode wrap” if TC crosses midnight

Bug Fixes

- › Crash with CDL server enabled
- › Fix issue with Livegrade CDL server
- › Export options don't take effect unless pane opened

Changes in version 2013.r1.2100 (25/03/2013)

New features

- › Filmlight CDL server is now enabled by default without sysconfig
- › Support for Canon C500 camera flip/flop settings
- › Support for Canon C500 HRAW sensor crop recording mode
- › Support for additional ARRI Alexa metadata
- › Support for Codex XR capture drives

Bug Fixes

- › Not possible to record CDL from an external server
- › Wrong LUT name shown on control UI
- › CDLs that are part of an ARRI look file are now handled separately
- › Playback of ARRIRAW after CANONRAW material doesn't work
- › Improved E-to-E handling of video signal disturbances